

Location ID	Date/Time	VOC (ppm)	LEL (%)	H2S (ppm)	CO (ppm)	O2 (%)	Particulates (ug/m3)	Benzene (ppm)	Xylene (ppm)	Toluene (ppm)	Naptha (ppm)	Comment	Location Type	Agency
1-1940	4/26/2019 1:11	0	0	0		20.9	12.2	0				La Porte Fire Department Station 2	Routine	EPA
1-1941	4/26/2019 1:20	0	0	0		20.9	11.6	0				Glen Meadows Park	Routine	EPA
1-1942	4/26/2019 1:30	0	0	0		20.9	11.8	0				Corner of Farrington and Meadow Cres	Routine	EPA
1-1943	4/26/2019 1:45	0	0	0		20.9	11.8	0				Bayshore Baptist Church	Routine	EPA
1-1944	4/26/2019 1:50	0	0	0		20.9	11.9	0				Corner Of Erin and Jessica	Routine	EPA
1-1945	4/26/2019 2:10	0	0	0		20.9	13.8	0				Fire Station on Sems Road	Routine	EPA
1-1946	4/26/2019 2:15	0	0	0		20.9	11.8	0				Grace Baptisy on North L	Routine	EPA
1-1947	4/26/2019 2:20	0	0	0		20.9	8.2	0				Lomax Elementary	School	EPA
1-1948	4/26/2019 2:45	0	0	0		20.9	14.8	0				Stripes on Spencer	Routine	EPA
1-1949	4/26/2019 3:00	0	0	0		20.9	12.2	0				Whataburger on 11th	Routine	EPA
1-1950	4/26/2019 3:30	0	0	0		20.9	7.2	0				Stripes on Fairmont	Routine	EPA
1-1951	4/26/2019 3:40	0	0	0		20.9	10.7	0				Corner of East 13th and East Blvd	Routine	EPA
1-1952	4/26/2019 4:25	0	0	0		20.9	12.2	0				Corner of Battleground and East X	Routine	EPA
1-1953	4/26/2019 4:45	0	0	0		20.9	13.8	0				Lomax Junior High	School	EPA
1-1954	4/26/2019 4:50	0	0	0		20.9	16.7	0				Lomax Elementary	School	EPA
1-1955	4/26/2019 5:00	0	0	0		20.9	14.2	0				Monument Baptist Church	Routine	EPA
1-1956	4/26/2019 8:46	0	0	0		20.9		0				13th and Independence	Routine	EPA
1-1957	4/26/2019 8:58	0	0	0		20.9		0				San Jacinto Elementary	School	EPA
1-1958	4/26/2019 9:07	0	0	0		20.9		0				E X St. and Karankawas Ct.	Routine	EPA
1-1959	4/26/2019 9:25	0	0	0		20.9		0				East X St and Oates Industries	Routine	EPA
1-1960	4/26/2019 9:34	0	0	0		20.9		0				North P St. and Willowview St.	Routine	EPA
1-1961	4/26/2019 9:43	0	0	0		20.9		0				Sens Rd - AT-PAC	Routine	EPA
3-487	4/26/2019 9:45	0	0	0	0	20.9		0				Kinder Morgan dock. Water surface is debris and product free, visibly. Confirmed with CTEH and NRC. 73F with 8mph winds from North.	Routine	EPA
1-1962	4/26/2019 9:53	0	0	0		20.9		0				Shirley Lane and North H St.	Routine	EPA
1-1963	4/26/2019 10:03	0	0	0		20.9		0				North H St. (dead end)	Routine	EPA
3-488	4/26/2019 10:07	0	0	0	0	20.9		0				BASF SHORE. Water turbid. Few visible pink green product blebs on surface. Debris on water. Confirmed with CTEH and NRC.	Routine	EPA
1-1964	4/26/2019 10:13	0	0	0		20.9		0				Lomax School Road (dead end north of N P St.)	Routine	EPA
3-489	4/26/2019 10:20	0	0	0	0	20.9		0				BASF channel. No visible debris or product on water. Low Turbidity. Confirmed with CTEH and NRC	Routine	EPA
3-490	4/26/2019 10:28	0	0	0	0	20.9		0				Kinder Morgan Channel. Cannot take spot at designated point because of low tide. Water surface free of any visible product or debris. Confirmed with CTEH and NRC	Routine	EPA
1-1965	4/26/2019 10:30	0	0	0		20.9		0				E. Pasadena and Underwood Rd.	Routine	EPA
1-1966	4/26/2019 10:38	0	0	0		20.9		0				Park Meadows Ave. and South Park Way Dr.	Routine	EPA
3-491	4/26/2019 10:47	0	0	0	0	20.9		0				Shell Bay mouth. Low water. Water turbid. Organic debris. Confirmed with CTEH and NRC	Routine	EPA
1-1967	4/26/2019 10:50	0	0	0		20.9		0				Deer Park Elementary School	School	EPA
3-492	4/26/2019 10:55	0	0	0	0	20.9		0				Shell Bay dock. Water surface free of any visible product or debris. Confirmed with CTEH and NRC	Routine	EPA
1-1968	4/26/2019 11:04	0	0	0		20.9		0				Deer Park High School (South Campus)	School	EPA
3-493	4/26/2019 11:08	0	0	0	0	20.9		0				Enterprise terminal shore. Water surface free of any visible product or debris. Low Turbidity. Tiny fish present. Confirmed with CTEH and NRC	Routine	EPA
3-494	4/26/2019 11:20	0	0	0	0	20.9		0				Enterprise terminal channel. No debris on water. Tiny blebs of product on water (0.5in>; 3 blebs> per square in.). Confirmed with CTEH and NRC	Routine	EPA
1-1969	4/26/2019 11:22	0	0	0		20.9		0				Estate St. and Kingsdale St.	Routine	EPA
1-1970	4/26/2019 11:36	0	0	0		20.9		0				Knob Hill Ave and Center St.	Routine	EPA
3-495	4/26/2019 11:40	0	0	0	0	20.9		0				Decontamination Depot. Visible product film on water surface. Some debris on water surface. Work boats docked nearby. workers present in level D PPE. Confirmed with CTEH and NRC	Routine	EPA
1-1971	4/26/2019 11:49	0	0	0		20.9		0				San Jacinto College Central	School	EPA
1-1972	4/26/2019 11:59	0	0	0		20.9		0				Pecan Park	Routine	EPA
3-496	4/26/2019 12:12	0	0	0	0	20.9		0				South Atlantic Services. Product film visible on water. Some debris on water surface. Water is relatively calm. Confirmed with CTEH and NRC	Routine	EPA
3-497	4/26/2019 12:15	0	0	0	0	20.9		0				South Atlantic Services. Inorganic debris on water. Confirmed with CTEH and NRC	Routine	EPA
1-1973	4/26/2019 12:16	0	0	0		20.9		0				Driveway of apartment complex east of Underwood Rd.	Routine	EPA
1-1974	4/26/2019 12:28	0	0	0		20.9		0				Farrington Park Swimming Pool Parking Lot	Routine	EPA
3-498	4/26/2019 12:30	0	0	0	0	20.6		0				Jacintoport dock. Port is boomed-off. Thin product film visible on water surface. Some debris on water. Odor smells of new sneakers. Confirmed with CTEH and NRC	Routine	EPA
3-499	4/26/2019 12:40	0	0	0	0	20.9		0				Jacintoport shore. Thin film of product visible on the water. No debris present on water. Confirmed with CTEH and NRC	Routine	EPA
1-1975	4/26/2019 12:43	0	0	0		20.9		0				Driftwood Drive and Spencer Hwy	Routine	EPA
3-500	4/26/2019 12:54	0	0	0	0	20.9		0				Tucker Bayou Mouth. Odor of benzene. Thin product film visible on water surface. organic debris. confirmed with CTEH and NRC	Routine	EPA
3-501	4/26/2019 13:06	0	0	0	0	20.9		0				Tucker Bayou Condemned dock. Smell of benzene more strong than at mouth. Thin product film visible on water surface. Debris on water. Confirmed with CTEH and NRC	Routine	EPA
3-502	4/26/2019 13:16	0	0	0	0	20.9		0				ITC dock 2. No product or debris observed on water surface. Workers are venting Benzene over at dock 7. Confirmed with CTEH and NRC	Routine	EPA

1-2029	4/27/2019 9:22	0	0	0		20.9	13.1	0
3-511	4/27/2019 9:22	0	0	0	0	20.9		0
3-512	4/27/2019 9:32	0	0	0	0	20.9		0
3-513	4/27/2019 9:38	0	0	0	0	20.9		0
1-2030	4/27/2019 9:39	0	0	0		20.9	29.2	0
1-2031	4/27/2019 9:52	0	0	0		20.9	15.5	0
3-514	4/27/2019 9:53	0	0	0	0	20.9		0
1-2032	4/27/2019 10:04	0	0	0		20.9	23.9	0
1-2033	4/27/2019 10:19	0	0	0		20.9	17.4	0
3-515	4/27/2019 10:20	0	0	0	0	20.9		0
3-516	4/27/2019 10:27	0	0	0	0	20.9		0
1-2034	4/27/2019 10:34	0	0	0		20.9	22.1	0
1-2035	4/27/2019 10:47	0	0	0		20.9	17.1	0
1-2036	4/27/2019 10:56	0	0	0		20.9	28	0
3-517	4/27/2019 11:09	0	0	0	0	20.9		0
3-518	4/27/2019 11:13	0	0	0	0	20.9		0
3-519	4/27/2019 11:24	0.1	0	0	0	20.9		0
1-2037	4/27/2019 11:25	0	0	0		20.9	18.5	0
3-520	4/27/2019 11:33	0	0	0	0	20.9		0
1-2038	4/27/2019 11:39	0	0	0		20.9	16.8	0
3-521	4/27/2019 11:40	0	0	0	0	20.9		0
3-522	4/27/2019 11:50	0	0	0	0	20.9		0
1-2039	4/27/2019 11:50	0	0	0		20.9	21.3	0
3-523	4/27/2019 11:55	0	0	0	0	20.9		0
1-2040	4/27/2019 12:01	0	0	0		20.9	28.7	0
3-524	4/27/2019 12:08	0	0	0	0	20.9		0
1-2041	4/27/2019 12:11	0	0	0		20.9	27.3	0
3-525	4/27/2019 12:22	0	0	0	0	20.9		0
3-526	4/27/2019 12:42	0	0	0	0	20.9		0
3-527	4/27/2019 13:07	0	0	0	0	20.9		0
3-528	4/27/2019 13:27	0	0	0	0	20.9		0
1-2042	4/27/2019 13:29	0	0	0		20.9	7.1	0
3-529	4/27/2019 13:44	0	0	0	0	20.9		0
1-2043	4/27/2019 13:53	0	0	0		20.9	32.4	0
3-530	4/27/2019 14:15	0	0	0	0	20.9		0
1-2044	4/27/2019 14:21	0	0	0		20.9	29.9	0
3-531	4/27/2019 14:35	0	0	0	0	20.9		0
3-532	4/27/2019 14:49	0	0	0	0	20.9		0
1-2045	4/27/2019 14:57	0	0	0		20.9	33.8	0
3-533	4/27/2019 15:00	0	0	0	0	20.9		0
3-534	4/27/2019 15:02	0	0	0	0	20.9		0

Dezavala Road at Kirby Gate 6	Routine	EPA
Houston oil Co barge. No visible debris or product on water surface. Confirmed with CTEH and NRC	Routine	EPA
Battleship park shore. Light product film visible on water surface. Debris visible on surface. soft booms deployed- saturated with something brown. confirmed with CTEH and NRC	Routine	EPA
Battleship park shore. Debris visible on water. Product blebs visible on water. Point is behind barge boat holding boom barge. Confirmed with CTEH and NRC	Routine	EPA
American Legion on Market Street	Routine	EPA
Market Street Bridge	Routine	EPA
Houston oil co shore. Flare stack began flaring as we entered bayou . Smelled like nail polish. Light product film and debris visible on water surface. confirmed with CTEH and NRC	Routine	EPA
Meadowbrook Park on River Road	Routine	EPA
Market Street at dead end	Routine	EPA
Hasco Marina. no product or debris visible on water. Diesel exhaust odors. Confirmed with CTEH and NRC	Routine	EPA
Cheryl K. Marina. No odors. no visible product or debris on water. oil lines on sea wall - old looking. confirmed with CTEH and NRC	Routine	EPA
River Road and Shields Street	Routine	EPA
River Terrace Park	Routine	EPA
River Terrace Park on Market Street	Routine	EPA
Vopak channel. Water is free of any visible debris and product. Single pink green bleb. Confirmed with CTEH and NRC	Routine	EPA
Vopak shore. water is turbid. Discontinuous light silver-sheen product film. debris visible on water. Got unsustained 0.5 ppm VOC reading with chemical odors coming with wind gusts. CTEH got 0.2 ppm max unsustained	Routine	EPA
Vopak terminal. Chemical odors persist coming with wind gusts from the West. 0.1 ppm VOC unsustained. Max 0.4 ppm. CTEH got unsustained Max of 0.3 ppm VOC. comes and goes with wind. Confirmed with CTEH and NRC	Routine	EPA
Dezavala elementary school on Euclid	School	EPA
Vopak Barge dock 2A. Product film visible on water. Debris present. Odors are faint. confirmed with CTEH and NRC	Routine	EPA
Peninsula Street at Coastal Cargo gate	Routine	EPA
ITC dock 8. Benzene odors coming crosswind from the red barge 29120. No visible debris or product on water surface	Routine	EPA
ITC dock 7. Right on Kirby barge 29120. barely visible thin product film on water. no debris on water. tiny fish in water. confirmed with CTEH and NRC	Routine	EPA
San Jacinto Blvd at Monument Chemical	Routine	EPA
ITC shore. Old product visible on the water mixed in with debris on water surface. No odors detected. confirmed with CTEH and NRC	Routine	EPA
Stolt Nielsen USA on Jacintoport blvd	Routine	EPA
ITC dock 12. product film on water. looks more thick than other film. debris on water. area is behind booms. confirmed with CTEH and NRC	Routine	EPA
Appelt Drive at Jacintoport blvd	Routine	EPA
ITC dock 2. Light swells of silver sheen product. No debris on the water. confirmed with CTEH and NRC	Routine	EPA
Tucker Bayou mouth. Product film on water. water is turbid. no debris on water. Confirmed with CTEH and NRC	Routine	EPA
Decontamination Depot. Barely hazy product visible on water surface. no debris visible on water surface. no chemical odors detected. confirmed with CTEH and NRC	Routine	EPA
Enterprise terminals shore. Light product sheen visible on water. looks evenly distributed. organic debris visible on water. confirmed with CTEH and NRC	Routine	EPA
River Terrace Park on Market Street	Routine	EPA
Enterprise Terminal channel. No visible product or debris on water surface. confirmed with CTEH and NRC	Routine	EPA
Lynchburg Ferry	Routine	EPA
Shell Bay mouth. Thin product film visible on water see.Organic debris on water. confirmed with CTEH and NRC	Routine	EPA
Independence Blvd at Monument Inn	Routine	EPA
Shell Bay dock. thin film of product visible on water. organic debris visible. confirmed with CTEH and NRC	Routine	EPA
Old Kinder Morgan dock. Thin, disseminated product film visible. no debris visible on water. confirmed with CTEH and NRC	Routine	EPA
Independence Blvd at Decker Dr	Routine	EPA
BASF Shore. product film visible on water. Debris visible on water. Confirmed with CTEH and NRC	Routine	EPA
BASF channel. No visible debris or product on water. Confirmed with CTEH and NRC	Routine	EPA

3-535	4/27/2019 15:12	0	0	0	0	20.9	31.4	0	Kinder Morgan channel. No visible product or debris on water surface. confirmed with CTEH and NRC	Routine	EPA	
3-536	4/27/2019 15:29	0	0	0	0	20.9		0	South Atlantic services shore. Thin product film visible on water surface. No debris on water surface. Confirmed with CTEH and NRC	Routine	EPA	
3-537	4/27/2019 15:38	0	0	0	0	20.9		0	South Atlantic Services channel. No visible product on water surface. Organic debris on water surface. Sunny, 82F, light wind, blue sky, altocumulus clouds. Confirmed with CTEH and NRC	Routine	EPA	
1-2046	4/27/2019 15:42	0	0	0		20.9		0	Meadow brook park	Routine	EPA	
3-538	4/27/2019 15:47	0	0	0	0	20.9		0	Jacintoport dock. Visible product film on water. Hardly any debris on water. Inflatable booms are as shoved to the side against the docks. container ship is docked. Confirmed with CTEH and NRC	Routine	EPA	
1-2047	4/27/2019 15:51	0	0	0		20.1		23.1	0	Magnolia Street at River Road	Routine	EPA
3-539	4/27/2019 15:57	0	0	0	0	20.9		0	Jacintoport shore. Visible product film on surface. Debris observed on water surface. Confirmed with CTEH and NRC	Routine	EPA	
1-2048	4/27/2019 16:05	0	0	0		20.9		30.9	0	Market Street at the dead end	Routine	EPA
1-2049	4/27/2019 16:19	0	0	0		20.9		24.7	0	River Terrace Park on Market Street	Routine	EPA
1-2050	4/27/2019 16:37	0	0	0		20.9		32.1	0	San Jacinto Blvd at Monument Chemical	Routine	EPA
1-2051	4/27/2019 16:50	0	0	0		20.9		32.8	0	Peninsula Street at Coastal Cargo gate	Routine	EPA
1-2052	4/27/2019 17:00	0	0	0		20.9		34.8	0	Houston Fuel Oil Terminal on Sheldon Road	Routine	EPA
1-2053	4/27/2019 17:13	0	0	0		20.9		28.9	0	Woodrow Street at West Elsbeth Road	Routine	EPA
1-2054	4/27/2019 17:23	0	0	0		20.9		17.1	0	Three Sisters Nursery on Bayou Drive	Routine	EPA
1-2055	4/27/2019 19:45	0	0	0		20.9			0	In parking lot,northwest side.	School	EPA
1-2056	4/27/2019 20:02	0	0	0		20.9			0	Wallisville road, northeast side	School	EPA
1-2057	4/27/2019 20:46	0	0	0		20.9			0	Welbeck Park	Routine	EPA
1-2058	4/27/2019 20:59	0	0	0		20.9			0	North shore Elementary school parking lot	School	EPA
1-2059	4/27/2019 21:15	0	0	0		20.9			0	Northshore rotary park off of Force Street	Routine	EPA
1-2060	4/27/2019 21:21	0	0	0		20.9			0	Cloverleaf park on Beacon Street	Routine	EPA
1-2061	4/27/2019 21:50	0	0	0		20.9		0	Endavour High School on Sheldon Road	School	EPA	
1-2062	4/27/2019 22:02	0	0	0		20.9		0	Flukenger Community Center, 10006 Lorenzo Street	Routine	EPA	
1-2063	4/27/2019 22:12	0.1	0	0		20.9		0	Marine Systems inc, at intersection of DeZavalla and Coolidge Street, slight benzene smell	Routine	EPA	
1-2064	4/27/2019 22:21	0	0	0		20.9		0	1025 LakesideDr. K-solve	Routine	EPA	
1-2065	4/27/2019 22:41	0	0	0		0		0	River Terrace Park, North	Routine	EPA	
1-2066	4/27/2019 22:52	0	0	0		20.9		0	Wild Hogs Eatery.	Routine	EPA	
1-2067	4/27/2019 23:28	0	0	0		20.9		0	Flying J truck stop	Routine	EPA	
1-2068	4/27/2019 23:36	0	0	0		20.9		0	American Legion on Market Street	Routine	EPA	
1-2069	4/27/2019 23:42	0	0	0		20.9		0	DeZavalla Elementary School	Routine	EPA	
1-2070	4/27/2019 23:59	0	0	0		20.9		0	Meadow brook Park	Routine	EPA	
1-2071	4/28/2019 0:16	0	0	0		20.9		0	FoodTown on Sheldon & I-10	Routine	EPA	
1-2072	4/28/2019 0:29	0	0	0		20.9		0	Trailer Park	Routine	EPA	
1-2073	4/28/2019 0:38	0	0	0		20.9		0	150808 Avenue C	Routine	EPA	
1-2074	4/28/2019 1:02	0	0	0		20.9		0	United Pentecostal church on Acadia	Routine	EPA	
1-2075	4/28/2019 1:14	0	0	0		0		0	United Methodist Church on East Freeway	Routine	EPA	
1-2076	4/28/2019 2:01	0	0	0		20.9		0	Bonanza Event Hall on Avenue C	Routine	EPA	
1-2077	4/28/2019 2:14	0	0	0		20.9		0	South Drive Baptist Church on South Drive	Routine	EPA	
1-2078	4/28/2019 2:20	0	0	0		20.9		0	Channellwood Park on Overbluff Street	Routine	EPA	
1-2079	4/28/2019 2:27	0	0	0		20.9		0	Sam Houston Elementary on Beltway 8	School	EPA	
1-2080	4/28/2019 2:39	0	0	0		20.9		0	Dell Dale Baptist Church on Dell Dale Ave.	Routine	EPA	
1-2081	4/28/2019 2:50	0	0	0		20.9		0	Fellowship of Purpose Church on Woodforest and Ashland	Routine	EPA	
1-2082	4/28/2019 2:57	0	0	0		20.9		0	St. Andrews Catholic Church on Sheldon Ave.	Routine	EPA	
1-2083	4/28/2019 3:04	0	0	0		20.9		0	Allison Johnson Jr High School on Procter	School	EPA	
1-2084	4/28/2019 3:17	0	0	0		20.9		0	US posts office on Sheldon	Routine	EPA	
1-2085	4/28/2019 3:29	0	0	0		20.9		0	2nd Baptist Church of Channelview on Dell Dale Ave	Routine	EPA	
1-2086	4/28/2019 3:38	0	0	0		0		0	Sterling Green South Park on Willersley	Routine	EPA	
1-2087	4/28/2019 3:49	0	0	0		20.9		0	Park on Hidden Park Lane	Routine	EPA	
1-2088	4/28/2019 4:04	0	0	0		20.9		0	Anthony Aguirre Jr. High School on Wallisville Rd.	School	EPA	
1-2089	4/28/2019 4:18	0	0	0		20.9		0	Terrace Park north on market Street	Routine	EPA	
1-2090	4/28/2019 4:27	0	0	0		20.9		0	1025 Lakeside Drive, K-Solv	Routine	EPA	
1-2091	4/28/2019 4:35	0	0	0		20.9		0	Marine ServicesInc on DeZavalla Dr.	Routine	EPA	
1-2092	4/28/2019 4:45	0	0	0		20.9		0	Flying J Truck Stop at Sheldon and Market	Routine	EPA	
1-2093	4/28/2019 9:00	0	0	0		20.9	13.3	0	Peninsula Street at the Coastal Cargo gate	Routine	EPA	
1-2094	4/28/2019 9:16	0	0	0		20.9	10.4	0	San jacinto Blvd at monument Chemical	Routine	EPA	
3-540	4/28/2019 9:16	0	0	0	0	20.9		0	Hasco Marine, Inc. Product film visible on water. Product appears to be pushed out from the wall when boat docks. Organic debris on water surface. Confirmed with CTEH and NRC	Routine	EPA	
3-541	4/28/2019 9:29	0	0	0	0	20.9		0	Thin product visible on water surface on both sides of soft booms. No debris present. Confirmed with CTEH and NRC	Routine	EPA	
3-542	4/28/2019 9:55	0	0	0	0	20.9		0	Houston oil co. barge. Visible product swirls on water. organic debris present. Confirmed with CTEH and NRC	Routine	EPA	

1-2095	4/28/2019 10:10	0	0	0		20.9	8.5	0
1-2096	4/28/2019 10:19	0	0	0		20.9	7.5	0
3-544	4/28/2019 10:20	0	0	0	0	20.9		0
3-545	4/28/2019 10:28	0	0	0	0	20.9		0
1-2097	4/28/2019 10:29	0	0	0		20.9	9.3	0
1-2098	4/28/2019 10:39	0	0	0		20.9	21.5	0
3-546	4/28/2019 10:48	0	0	0	0	20.9		0
1-2099	4/28/2019 10:52	0	0	0		20.9	5.6	0
3-547	4/28/2019 10:56	0	0	0	0	20.9		0
1-2100	4/28/2019 11:05	0	0	0		20.9	11.8	0
3-548	4/28/2019 11:11	0	0	0	0	20.9		0
1-2101	4/28/2019 11:14	0	0	0		20.9	12.2	0
3-549	4/28/2019 11:28	0	0	0	0	20.9		0
1-2102	4/28/2019 11:33	0	0	0		20.9	16.5	0
3-550	4/28/2019 11:34	0	0	0	0	20.9		0
3-551	4/28/2019 11:42	0	0	0	0	20.9		0
1-2103	4/28/2019 11:44	0	0	0		20.9	10.9	0
1-2104	4/28/2019 11:52	0	0	0		20.9	17.3	0
3-552	4/28/2019 11:53	0	0	0	0	20.9		0
1-2105	4/28/2019 12:00	0	0	0		20.9	19.1	0
3-553	4/28/2019 12:03	0	0	0	0	20.9		0
3-554	4/28/2019 12:14	0	0	0	0	20.9		0
1-2106	4/28/2019 12:22	0	0	0		20.9	14.1	0
3-555	4/28/2019 12:22	0	0	0	0	20.9		0
1-2107	4/28/2019 12:36	0	0	0		20.9	12.3	0
3-556	4/28/2019 12:41	0	0	0	0	20.9		0
1-2108	4/28/2019 12:48	0	0	0		20.9	12.1	0
3-557	4/28/2019 12:58	0	0	0	0	20.9		0
1-2109	4/28/2019 12:59	0	0	0		20.9	20.5	0
3-558	4/28/2019 13:03	0	0	0	0	20.9		0
1-2110	4/28/2019 13:09	0	0	0		20.9	17.8	0
1-2111	4/28/2019 14:12	0	0	0		0	14.1	0
1-2112	4/28/2019 14:23	0	0	0		20.9	31.8	0
1-2113	4/28/2019 14:49	0	0	0		20.9	27.1	0
1-2114	4/28/2019 14:59	0	0	0		20.9	14.8	0
3-559	4/28/2019 15:05	0	0	0	0	20.9		0
1-2115	4/28/2019 15:09	0	0	0		20.9	17.1	0
3-560	4/28/2019 15:15	0	0	0	0	20.9		0
1-2116	4/28/2019 15:20	0	0	0		20.9	15.2	0
3-561	4/28/2019 15:24	0	0	0	0	20.9		0
1-2117	4/28/2019 15:28	0	0	0		20.9	17.8	0
1-2118	4/28/2019 15:35	0	0	0		20.9	28.4	0
1-2119	4/28/2019 15:46	0	0	0		20.9	12.7	0
1-2120	4/28/2019 16:02	0	0	0		20.9	14.1	0
1-2121	4/28/2019 16:12	0	0	0		20.9	20.4	0
1-2122	4/28/2019 16:22	0	0	0		20.9	18.3	0
1-2123	4/28/2019 20:30	0	0	0		20.9	6.1	0
1-2124	4/28/2019 20:40	0	0	0		20.9	6.8	0
1-2125	4/28/2019 21:10	0	0	0		20.9	9.6	0
1-2126	4/28/2019 21:20	0	0	0		20.9	7.8	0

Magnolia Street at River Road	Routine	EPA
Meadow brook park on Park Drive	Routine	EPA
Battleship park boom barge. winds coming from the south. Thin product film visible. No organic debris present. confirmed with CTEH and NRC	Routine	EPA
Houston oil Co. shore. Barely discernable product on water surface. organic debris on water. low wind. Confirmed with CTEH and NRC	Routine	EPA
Market Street at the Bridge	Routine	EPA
Market Street at dead end	Routine	EPA
Vopak channel. Visible pink-green product ribbons on water surface . No debris on water. Confirmed with CTEH and NRC	Routine	EPA
River Terrace Park on Market Street	Routine	EPA
Vopak shore. Visible product coming from under raised shore brick material and trailing around side of boat. debris present on water. confirmed with CTEH and NRC	Routine	EPA
Lakeside drive and n shore Avenue	Routine	EPA
Vopak Barge Dock 2A. no visible product or debris on water. wind has increased in speed. Confirmed with CTEH and NRC	Routine	EPA
DeZavala road at the DeZavala cemetery	Routine	EPA
ITC Dock 8. Detected benzene odors coming on winds from SE. 0.225 ppm benzene with Weston and CTEH instruments. TCEQ got 0.2 ppm benzene. VOC peak was 0.5 ppm (CTEH) and 0.2 ppm (Weston) and 0.1 (TCEQ) unsustainable. CTEH logging theirs as sustained. Pink-green sheen across water	Routine	EPA
McCarthy on Market Street	Routine	EPA
ITC Dock 7. Parked near Kirby barge 29120. Unsustained 0.1 ppm VOC. No visible sheen or debris on water. Confirmed with CTEH and NRC	Routine	EPA
ITC shore. Thin product swirls and ribbons visible on water. Debris present. Confirmed with CTEH and NRC	Routine	EPA
Appelt Drive at Cleaver Brooks	Routine	EPA
BR&L on Jacintoport Blvd	Routine	EPA
ITC Dock 2. No visible product or debris. Confirmed with CTEH and NRC	Routine	EPA
Jacintoport Blvd at San jacinto Blvd	Routine	EPA
Tucker Bayou Mouth. No debris on water. Product ribbons and spots appear on water surface when water laps up on or under shore rocks. Confirmed with CTEH and NRC.	Routine	EPA
Jacintoport dock. Visible product film on water. Small amount of debris present. Booms are shoved under the dock. No ship docked. Confirmed with CTEH and NRC	Routine	EPA
Schochler Elementary school on Deerpass Street	School	EPA
Jacintoport West point. Visible sheen on water. faint benzene odor. Product on rocks on shore. Some organic debris on water. Confirmed with CTEH and NRC	Routine	EPA
Taranto Lane at circle	Routine	EPA
Jacintoport shore. Product film visible on water. No debris on water. Crabs hiding in shore bricks. about 9 mph winds. Confirmed with CTEH and NRC	Routine	EPA
Beacon Street and Waxahachie Street	Routine	EPA
South Atlantic Services shore. Visible product film on water. no debris present. chemical odors. Confirmed with CTEH and NRC	Routine	EPA
Bandera Street and Freeport Street	Routine	EPA
South Atlantic Services channel. No visible debris or product on water. Confirmed with CTEH and NRC	Routine	EPA
Freeport Street at Victoria Street	Routine	EPA
Bandera Street west of Evanston Street	Routine	EPA
North Shore 9th Grade Campus on Hollypark Drive	School	EPA
Force Street and Frankie Street	Routine	EPA
Laredo Street and Beacon Street	Routine	EPA
Shell Bay mouth. No visible product or debris on water. Some thin product film and debris trapped behind mooring dock. confirmed with CTEH and NRC.	Routine	EPA
Garber Lane and Cloverleaf Street	Routine	EPA
Shell Bay dock. Visible product and organic film clinging to dock. Some debris present. Confirmed with CTEH and NRC	Routine	EPA
Nimits Street and Beacon Street	Routine	EPA
Old Kinder Morgan Dock. Water is free of debris and product. Confirmed with CTEH and NRC	Routine	EPA
Topeka Street	Routine	EPA
Uvalde Road and Indianapolis Street	Routine	EPA
Uvalde Road and Woodforest Blvd	Routine	EPA
Fintona Way at the Circle	Routine	EPA
Crosshaven Dr and Evanston Street	Routine	EPA
Skate Machine on Longview Street	Routine	EPA
Exxon on Dell Dale	Routine	EPA
Channelwood Park	Routine	EPA
South Drive Baptist Church	Routine	EPA
Cobb Elementary on Dell Dale	School	EPA

1-2127	4/28/2019 21:30	0	0	0	20.9	7.8	0
1-2128	4/28/2019 21:45	0	0	0	20.9	13.8	0
1-2129	4/28/2019 22:10	0	0	0	20.9	12.2	0
1-2130	4/28/2019 22:15	0	0	0	20.9	6.8	0
1-2131	4/28/2019 22:35	0	0	0	20.9	11.9	0
1-2132	4/28/2019 22:40	0	0	0	20.9	13.8	0
1-2133	4/28/2019 22:50	0	0	0	20.9	12.2	0
1-2134	4/28/2019 23:01	0	0	0	20.9	11.3	0
1-2135	4/28/2019 23:05	0	0	0	20.9	12.8	0
1-2136	4/28/2019 23:10	0	0	0	20.9	11.9	0
1-2137	4/28/2019 23:15	0	0	0	20.9	14.2	0
1-2138	4/28/2019 23:25	0	0	0	20.9	11.8	0

Second Baptist Channelview	Routine	EPA
Bonanza Event Hall	Routine	EPA
Flying J on Sheldon	Routine	EPA
Corner of Market and Grand	Routine	EPA
Flukinger Community Center	Routine	EPA
Channelview Fire Department on Market	Routine	EPA
Wild Hawgs on Market	Routine	EPA
River Terrace Park North	Routine	EPA
Corner of Pecan and Lakeside Dr	Routine	EPA
1025 Lakeside Dr	Routine	EPA
Marine Systems Inc	Routine	EPA
Dezavala Elementary School	School	EPA